## Message Text

LIMITED OFFICIAL USE

PAGE 01 ISLAMA 08235 271331Z

50

ACTION TRSE-00

INFO OCT-01 EA-11 NEA-14 ISO-00 IO-14 SP-03 AID-20 EB-11

NSC-07 RSC-01 CIEP-03 SS-20 STR-08 OMB-01 CEA-02

CIAE-00 COME-00 FRB-03 INR-11 NSAE-00 XMB-07 OPIC-12

LAB-06 SIL-01 INT-08 L-03 H-03 PA-04 PRS-01 USIA-15

DRC-01 /191 W

----- 070592

R 271135Z AUG 74 FM AMEMBASSY ISLAMABAD TO SECSTATE WASHDC 6460 INFO AMCONSUL KARACHI AMCONSUL LAHORE

NEJMA/AMEMBASSY MANILA 592

LIMITED OFFICIAL USE ISLAMABAD 8235

MANILA PASS USADB

E.O. 11652: N/A TAGS: ECRE, EFIN, PK

SUBJECT: TARBELA DAM PROBLEMS

REF: ISLAMABAD 8105

1 SUMMARY: NEW EVIDENCE INDICATES POTENTIALLY SERIOUS DAMAGE TO TUNNEL TWO RESULTING IN DECISION TO UTILIZE ALL FOUR TUNNELS TO DRAWDOWN RESERVOIR LEVEL. UNTIL RESERVOIR DRAINED TO TUNNEL LEVEL PERMITTING ACCESS BY ENGINEERS, IT IS NOT RPT NOT POSSIBLE TO EVALUATE TIME OR COST OF REPAIRS. END SUMMARY.

2.ON AUGUST 24 LARGE PIECES OF CONCRETE AND REINFORCING ROD WERE OBSERVED COMING FROM TUNNEL TWO. DECISION THEN LIMITED OFFICIAL USE

LIMITED OFFICIAL USE

PAGE 02 ISLAMA 08235 271331Z

MADE TO OPEN TUNNELS THREE AND FOUR WHICH HAD ALREADY

SUFFERED CONCRETE EROSION IN ORDER TO DRAIN RESERVOIR AS FAST AS POSSIBLE. NOW ALL FOUR TUNNELS ARE DISCHARGING. TO MINIMIZE EROSION DAMAGE ON TUNNELS THREE AND FOUR, ONE OF TWOOUTLET GATES ON EACH TUNNEL REMAINS CLOSED. CREWS PRESENTLY TEARING OUT ERODED AREAS BELOW THESE CLOSED GATES TO EXPEDITE REPAIRS IN ORDER TO UTILIZE THESE CHANNELS FOR RIVER FLOW DURING THE REPAIRS TO TUNNELS ONE AND TWO AND THE OTHER OUTLET GATE AREAS OF TUNNELS THREE AND FOUR.

- 3. TUNNELS PRESENTLY DISCHARGING AT RATE OF 383,000 CUSECS. IN TWO DAYS RESERVOIR ELEVATION LOWERED 29 FEET. IF RIVER IN FLOW REMAINS AT RECENT AVERAGE AND NO FURTHER TUNNEL PROBLEMS ENCOUNTERED REQURING CLOSURES, DRAWDOWN COULD BE COMPLETED WITHIN TWO-THREE WEEKS. HOWEVER, ENGINEERS WILL ONLY COMMIT THEMSELVES TO DRAWDOWN BY OCTOBER 1. REASONABLE ESTIMATE OF TIME AND COST REQUIRED FOR REPAIRS WILL ONLY BE AVAILABLE APPROXIMATELY TWO WEEKS AFTER ENGINEERS HAVE ACCESS TO TUNNEL ONE AND TWO GATES. AS THESE TUNNEL INLETS ARE SLIGHTLY LOWER THAN INLETS TO TUNNELS THREE AND FOUR, FULL ACCESS TO GATES MAY REQUIRE PLUGGING TUNNEL INLETS.
- 4. ON VISIT TO SITE AUGUST 21 PRIOR TO SURFACING OF LATEST PROBLEMS, MISSION OFFICERS WERE TOLD THAT TUNNEL PROBLEMS SHOULD CAUSE NO DELAY IN POWER HOUSE CONSTRUCTION. REASON GIVEN WAS THAT TUNNELS ONE AND TWO WOULD HAVE TO BE SHUTDOWN IN ANY CASE FOR INSTALATION MAIN TUNNEL GATES AND DIVERSION FACILITIES ON TUNNEL ONE FROM PRESENT OUTLET INTO POWER HOUSE. ESTIMATE THEN WAS THAT FLOW THROUGH TUNNEL ONE INTO POWER HOUSE FOR TESTING PURPOSES WOULD NOT BE REQUIRED UNTIL LATE 1976. IT WAS BELIEVED THAT ANY REPAIRS COULD BE COMPLETED BY THAT TIME. DELAYS KNOWN PREVIOUSLY IN DELIVERY OF POWER HOUSE EQUIPMENT RESULTED IN THREE-MONTH SLIPPAGE IN COMPLETION DATE.
- 5. EMBASSY HAS HEARD ROUGH GUESSTIMATES FROM ENGINEERS OF POSSIBLE COST OF REPAIRS IN RANGE US \$5-100 MILLION. IBRD RESIDENT REPRESENTATIVE OBSERVED TO EMBOFF THAT RELATIVE TO TOTAL COST OF PROJECT AND PROBLEMS ENCOUNTERED LIMITED OFFICIAL USE

LIMITED OFFICIAL USE

PAGE 03 ISLAMA 08235 271331Z

IN OTHER CONSTRUCTION PROJECTS OF THIS SIZE, EVEN \$100 MILLION IS NOT DISASTROUS.

6. RECOMMEND ANYONE FOLLOWING THIS PROBLEM IN WASHINGTON MAINTAIN CLOSE CONTACT WITH IBRD WHICH IS RECEIVING FREQUENT REPORTS DIRECTLY FROM GIBBS, TAMS AND HARZA. BYROADE

LIMITED OFFICIAL USE

NNN

## Message Attributes

Automatic Decaptioning: X Capture Date: 01 JAN 1994 Channel Indicators: n/a

**Current Classification: UNCLASSIFIED** Concepts: CONSTRUCTION, DAMS

Control Number: n/a Copy: SINGLE Draft Date: 27 AUG 1974 Decaption Date: 01 JAN 1960 Decaption Note: Disposition Action: RELEASED Disposition Action: RELEASED
Disposition Approved on Date:
Disposition Authority: martinml
Disposition Case Number: n/a
Disposition Comment: 25 YEAR REVIEW
Disposition Date: 28 MAY 2004
Disposition Event:
Disposition History: n/a
Disposition Reason:
Disposition Remarks:
Document Number: 1974|SLAMA08235

Document Number: 1974ISLAMA08235 Document Source: CORE Document Unique ID: 00 Drafter: n/a

Enclosure: n/a Executive Order: N/A Errors: N/A Film Number: D740236-0902 From: ISLAMABAD Handling Restrictions: n/a

Image Path:

Legacy Key: link1974/newtext/t19740815/aaaaamtm.tel Line Count: 114 Locator: TEXT ON-LINE, ON MICROFILM

Office: ACTION TRSE

Original Classification: LIMITED OFFICIAL USE

Original Handling Restrictions: n/a Original Previous Classification: n/a Original Previous Handling Restrictions: n/a

Page Count: 3

Previous Channel Indicators: n/a
Previous Classification: LIMITED OFFICIAL USE

Previous Handling Restrictions: n/a Reference: ISLAMABAD 8105 Review Action: RELEASED, APPROVED
Review Authority: martinml

Review Comment: n/a Review Content Flags: Review Date: 09 AUG 2002

**Review Event:** 

Review Exemptions: n/a
Review History: RELEASED <09-Aug-2002 by worrelsw>; APPROVED <05 MAR 2003 by martinml>

**Review Markings:** 

Declassified/Released US Department of State EO Systematic Review 30 JUN 2005

**Review Media Identifier:** Review Referrals: n/a Review Release Date: n/a Review Release Event: n/a **Review Transfer Date:** Review Withdrawn Fields: n/a

Secure: OPEN Status: NATIVE

Subject: TARBELA DAM PROBLEMS

TAGS: ECRE, EFIN, PK, US

To: STATE

Type: TE

Markings: Declassified/Released US Department of State EO Systematic Review 30 JUN 2005